



Executive Engineer
Byatarayanapura Sub Division
B.B.M.P. Bangalore-560024

Work Order - View

Scanned by CamScanner

Name of Work: Improvements to Drains and Asphalting to Roads in Sriram pura, MCLCHS Layout, Telicom Layout Sarrounding Area in Ward No. 05 Byatarayanapura Sub Division.

	Decimal	DMS
Latitude	13.070409	13°4'13" N
Longitude	77.622191	77°37'19" E

1212, 19th Cross Rd, Sri Balaji Krupa Layout, RK Hegde Nagar, Bengaluru, Karnataka 560077, India

	Decimal	DMS
Latitude	13.071878	13°4'18" N
Longitude	77.622115	77°37'19" E

Executive Engineer
Byatarayanapura Sub Division
B.B.M.P Bangalore-560024

Scanned by CamScanner

Name of Work: Improvements to Drains and Asphalting to Roads in Sriram para [illegible] Layout,Telicom Layout Surrounding Area in Ward No. 05 Byatarayanapura Sub Division.



	Decimal	DMS
Latitude	13.070607	13°4'14" N
Longitude	77.621873	77°37'18" E

	Decimal	DMS
Latitude	13.066926	13°4'0" N
Longitude	77.625831	77°37'32" E

Assistant Executive Engineer
Byatarayanapura Sub Division
B.B.M.P. Bangalore-560024

Scanned by CamScanner

Name of WORK: Improvements to Drains and Asphalting to Roads in Sriram pura, MCHCHS - Layout, Telicom Layout Sarrounding Area in Ward No: 05 Byatarayanapura Sub Division.





Executive Engineer
Sub Division

Scanned by CamScanner